

01-022-N11B-7544

RECEIVED
BY USA-37

730 JAN 25 10 10 AM

FREIGHTLINER®
CORPORATION

Bob Johnson
Sr. Compliance Analyst
Product Compliance

ORIGINAL

IFU

1 pg

Freightliner Corporation
4747 N Channel
Portland, OR 97208-3849
503-735-5076 Phone
503-735-5544 Fax
Bobjohnson@freightliner.com

January 21, 2000

National Highway Traffic Safety Administration
Attention: VIN Coordinator, Room 5321
400 Seventh Street SW
Washington, DC 20590

Subject: Amended VIN Coding

In accordance with Part 565.7, Freightliner submits the following VIN deciphering information.

Page 4 VIN position 5 code changed for Freightliner

<u>Code</u>	<u>Model</u>	<u>Cab</u>
Y	MB80	Conventional (Model year 1998 and before)
Y	T-2 Low cab Forward	COE (Model year 2001 and after)

Page 5 VIN position 5 new code for Sterling

X T-2 Low cab Forward COE

You may call me at (503) 735-5076 or fax at (503) 735-5544 if more information is needed.

Sincerely,



Bob Johnson
Compliance Analyst